

## GPS High Frequency firmware development

### **WARNING:**

The update GPS High Frequency firmware must be made with Toplink software V15 or superior version.

- V1.1
  - Correction calculation declination.
  
- V1.5
  - Fixed a bug of not acquiring cold start (backup battery discharged).  
Note: that the display for the position may be greater than 4 minute after cold start.
  - Allows the setting of filtering of the COG and SOG with a Multigraphic  $\geq$  V1.3 .
  - Used to reset the gps with a Mulyigraphic  $\geq$  V1.3
  
- V2.1     **Switch OFF/ON after update.**
  - Fixed a bug by setting filtering on the SOG and COG with the Multigraphic.