

## Heel angle sensor firmware evolution

- V1.2 NO COMPATIBLE PROCESSOR
  - Fixed bug