

Fluxgate Compass Sensor firmware development.

- V1.7 PROCESSOR COMPATIBLE
 - Increase the filtering during the autocompensation to limit the failures.
 - When a PROCESSOR is detected on the bus Topline, the compass remains dumb.
- V1.8 PROCESSOR COMPATIBLE
 - Fixed a bug of filtering after the autocompensation.