

SL50 firmware development

- V1.3 PROCESSOR COMPATIBLE
 - Compatibility with Processor
- V1.4 PROCESSOR COMPATIBLE
 - Masking of the defect "master missing" so the SL50 can continue to display the data