

## **TL25 firmware development**

- V2.2 PROCESSOR COMPATIBLE
  - Fixed bug causing a failure to receive NMEA
  - Addition of the declination, true heading and TWD channels
- V2.3 PROCESSOR COMPATIBLE
  - Addition of the acquisition of the magnetic declination in the RMC sentence
  - Correction of the label used for the display of the direction of the true wind 'TWD MAG' instead of "TRUE WIND D".