

WiFi Box firmware development

- V1.4
 - Added RMC sentence on the wired NMEA output and WiFi
 - Added check of GPS position to filter the glitches on the latitude and longitude
 - Added of the setting of the baudrate (from 4800 to 57600 baud) of the NMEA OUTPUT by Toplink.
 - Fixed a bug on the update dynamic channels (PNKEA sentence)
- V1.5
 - Fixed a bug on the nmea input
- V1.6
 - Fixed a bug on the RMB NMEA sentence, on the NMEA Output and WiFi .